

Brn: 5 to 12 VDC
 Blu: 0 V(com)
 Blk: Out A
 Wht: Out B
 Org: Out Z

Rotary Tach
 Connections

From
 Power
 Supply

Motor

Rotary
 Tach

